Tax key number: 59008094421

Property address: N4338 Claver Ct

Traffic / water / sanitary: Light / Well water / Septic

Legal description: LOT 1 CSM V26 P204-206 #1991349 - PRT SE NE, SEC 12.


Summary of Assessment				
Land	\$73,400			
Improvements	\$270,000			
Total value	\$343,400			

						Land			
Qty	Land Use	Width	Depth	Square Feet	Acres	Water Frontage	Tax Class	Special Tax Program	Assess Value
1	Residential			275,299	6.320	Pond (Prime)	Residential		\$72,100
1	1st grade tillable			217,800	5.000	None	1st grade tillable		\$1,300

				- · ·
	100=			Resider
Year built:	1987	Full basement:	936 SF	
Year remodeled:	1993	Crawl space:	624 SF	
Stories:	1 story	Rec room (rating):	468 SF	(AV)
Style:	Ranch	Fin bsmt living area:		
Use:	Single family	First floor:	1,560 SF	
Exterior wall:	Alum/vinyl	Second floor:		
Masonry adjust:		Third floor:		
Roof type:	Asphalt shingles	Half story:	0 SF	
Heating:	Gas, forced air	Finished attic:		
Cooling:	A/C, same ducts	Unfinished attic:		
Bedrooms:	_3	Unfinished area:		
Family rooms:		Patio	264 SF	
Baths:	2 full, 0 half	Enclosed porch	64 SF	
Other rooms:		Free Standing Stove	1 units	
Whirl / hot tubs:				
Add'l plumb fixt:				
Masonry FPs:				
Metal FPs:				
Gas only FPs:				
Bsmt garage:		Grade:	С	
Shed dormers:		Condition:	Average	
Gable/hip dorm:		Percent complete:	100%	



Total living area is 1,560 SF; building assessed value is \$213,500



## 2023 Property Records for Town of Lima, Sheboygan County

	Other Building Improvement (OBI)				
M	ain Structure		Modifications (Type, Size)	Photograph	
OBI type: Pond Const type: Standard Pond Year built: 2010	Units: 1	Grade: C Condition: Average % complete: 100% Assessed \$: \$4,000			

# of identical OBIs: 1		Other Building Improver	ment (OBI)	
Mai	in Structure		Modifications (Type, Size)	Photograph
OBI type: Lean-to Const type: Pole frame, metal siding Year built: 1999	Width: 20 LF Depth: 54 LF Floor area: 1,080 SF Height: 10 LF	Grade: C Condition: Average % complete: 100% Assessed \$: \$2,600		AT 171

# of identical OBIs: 1		Other Building Improver	ment (OBI)	
M	ain Structure	Modifications (Type, Size)	Photograph	
OBI type: Farm implement building, pole Const type: Pole frame, metal siding Year built: 1999	Width: 58 LF Depth: 54 LF Floor area: 3,132 SF Height: 12 LF	Grade: C Condition: Fair % complete: 100% Assessed \$: \$19,800		NO 3787

# of identical OBIs: 1		Other Building Improveme	nt (OBI)	
	Main Structure		Modifications (Type, Size)	Photograph
OBI type: Garage Const type: Detached, pole frame Year built: 1999	Width: 36 LF Depth: 30 LF Floor area: 1,080 SF Height: 0 LF	Grade: C Condition: Average % complete: 100% Assessed \$: \$12,200		

# of identical OBIs: 1		Other Building Improvem	nent (OBI)	
	Main Structure		Modifications (Type, Size)	Photograph
OBI type: Garage Const type: Detached, frame or cb Year built: 2000	Width: 24 LF Depth: 30 LF Floor area: 720 SF Height: 0 LF	Grade: C Condition: Average % complete: 100% Assessed \$: \$12,900		

## 2023 Property Records for Town of Lima, Sheboygan County

	Other Building Improvement (OBI)					
Main Structure				Modifications (Type, Size)	Photograph	
OBI type: Const type: Year built:	Septic Conventional	Units:	1	Grade: Condition: % complete: Assessed \$:		not available

Other Building Improvement (OBI)				
Ma	ain Structure	Modifications (Type, Size)	Photograph	
OBI type: Well Const type: Drilled Year built:	Units: 1	Grade: C Condition: Average % complete: 100% Assessed \$: \$2,500		not available

Building Permits				
Issued	Permit #	Purpose	\$ Amount	Completed
9/28/2018	18202	Re-roof, siding	\$14,840	1/1/2019

Sales History				
Date	Price	Туре		