November 3, 2022

\$130,600

\$205,300

\$335,900

Summary of Assessment

Land

Improvements

Total value

Tax key number: 59016221090


Property address: N5583 Oak Rd

Traffic / water / sanitary: Light / Well water / Septic Legal description: SW NE,SEC 29,EXC THE N 16.5' OF SD1/4,& EXC THE S 270'OF THE W 177'OF SW NE.

						Land			
Qty	Land Use	Width	Depth	Square Feet	Acres	Water Frontage	Tax Class	Special Tax Program	Assess Value
1	Residential			174,240	4.000	None	Residential		\$79,000
1	2nd grade tillable			914,760	21.000	None	2nd grade tillable		\$4,000
1	2nd grade tillable		I	566,280	13.000	None	Undeveloped	· 	\$47,500
1	Road ROW			17,424	0.400	None	Undeveloped		\$100

				F	tesidential Building
Year built: Year remodeled:	1961	Full basement: Crawl space:		1,344 SF	
Stories:	1 story	Rec room (rating):			
Style:	Ranch (Pre 1970)	Fin bsmt living area:			
Use:	Single family	First floor:		1,608 SF	
Exterior wall:	Wood	Second floor:			
Masonry adjust:	150 SF	Third floor:			
Roof type:	Asphalt shingles	Half story:	0 SF		
Heating:	Gas, forced air	Finished attic:			
Cooling:	A/C, same ducts	Unfinished attic:			
Bedrooms:	4	Unfinished area:			
Family rooms:		Garage		484 SF	
Baths:	1 full, 1 half	Open porch		30 SF	
Other rooms:		Patio		270 SF	
Whirl / hot tubs:					
Add'l plumb fixt:					
Masonry FPs:					
Metal FPs:					
Gas only FPs:		Crada	C		
Bsmt garage: Shed dormers:		Grade:			
			Average 100%		9/23/22, 9:08:38 AM 59016221090
Gable/hip dorm:		Percent complete:	100%		Tatal living area is 1 600 SEr hvilding assessed value is \$102 000

Total living area is 1,608 SF; building assessed value is \$183,000



# of identica	al OBIs: 1		Other Building Improver	nent (OBI)	
	N	lain Structure	Modifications (Type, Size)	Photograph	
OBI type: Const type: Year built:	Utility shed, residential Frame 1960	Width: 14 LF Depth: 11 LF Floor area: 154 SF	Grade: D Condition: Average % complete: 100% Assessed \$: \$500		

Other Building Improvement (OBI)							
N	lain Structure		Modifications (Type, Size)	Photograph			
OBI type: Well Const type: Drilled Year built: 1980	Units: 1	Grade: C Condition: Average % complete: 100% Assessed \$: \$3,000		not available			

	Other Building Improvement (OBI)							
	Main Structure Modifications (Type, Size) Photograph							
	Septic System	Units:	1	Grade:	С			
Const type:	Conventional			Condition:	Average		not available	
Year built:	1980			% complete:	100%			
				Assessed \$:	\$3,000			

# of identical OBIs: 1		Other Building Improver	ment (OBI)	
	Main Structure	Modifications (Type, Size)	Photograph	
OBI type: Barn, general purpose	Width: 36 LF	Grade: D		
Const type: Bank, wood	Depth: 54 LF	Condition: Fair		and the second sec
Year built: 1900	Floor area: 1,944 SF	% complete: 100%		
	Height: 24 LF	Assessed \$: \$9,900		

# of identical OBIs: 1		Other Build	ling Improven	nent (OBI)	
M	ain Structure			Modifications (Type, Size)	Photograph
OBI type: Lean-to Const type: Wood frame, wood siding Year built: 1900	Width: 10 LF Depth: 36 LF Floor area: 360 SF Height: 8 LF	Grade: Condition: % complete: Assessed \$:			

# of identica	al OBIs: 1		Other Building Improven	nent (OBI)	
		ain Structure		Modifications (Type, Size)	Photograph
OBI type: Const type: Year built:	Farm utility building, pole Wood, 4 sides closed 1900	Width: 8 LF Depth: 14 LF Floor area: 112 SF Height: 10 LF	Grade: C Condition: Fair % complete: 100% Assessed \$: \$300		
# of identica	al OBIs: 1		Other Building Improven	nent (OBI)	
		ain Structure		Modifications (Type, Size)	Photograph
OBI type: Const type: Year built:	Farm utility building, pole Wood, 1 side open 1900	Width: 50 LF Depth: 60 LF Floor area: 3,000 SF Height: 12 LF	Grade: C Condition: Fair % complete: 100% Assessed \$: \$3,800		
# of identica	al OBIs: 1		Other Building Improven	nent (OBI)	
		ain Structure	v ,	Modifications (Type, Size)	Photograph
OBI type: Const type: Year built:	Detached Decks/Porches/Patios Wood Deck 1990	Width: 12 LF Depth: 24 LF Floor area: 288 SF	Grade: C Condition: Average % complete: 100% Assessed \$: \$1,200		
# of identics	al OBIs: 1		Other Building Improven	ent (OBI)	
		ain Structure		Modifications (Type, Size)	Photograph
OBI type: Const type: Year built:	Silo, concrete Poured, with roof 1930	Diameter: 14 LF Height: 30 LF Volume: 4,620 CF	Grade: C Condition: Unusable % complete: 100% Assessed \$: \$100		
# of identica	al OBIs: 1		Other Building Improven	nent (OBI)	
		ain Structure		Modifications (Type, Size)	Photograph
OBI type: Const type: Year built:	Silo, concrete Poured, with roof 1930	Diameter: 14 LF Height: 30 LF Volume: 4,620 CF	Grade: C Condition: Unusable % complete: 100% Assessed \$: \$100		

- Carles and allowed

		Building Permits	Sales History				
Issued	Issued Permit # Purpose \$Amount Completed					Price	Туре
7/21/2015	42-15	Repairs from water damage	\$20,000	1/1/2016	10/30/2015	\$280,000	Not a market sale
		·	12/15/2000	\$183,300	Valid improved sale		