

SELLER HOME UPDATES

Updates and Repairs Summer of 2025.

1. Electrical Updates and repairs throughout the home.
2. Install Fire separation wall Fire door between house and garage.
3. Chimney Repairs
4. Removal of Exterior Faucet.
5. Vent fan installed in attic to provide outside insulation.

All of the above work was done by licensed contractors.